CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
	Northeast Corner of Section	
STATE OF MINNESOTA, County ofYellow Medicine		
At the corner location shown on the sketch:		
K	On <u>Apr. 28. 1976</u> found a <u>6"x6"x24" a</u> DATE surface.	concrete monument 18" below the road
	🗵 left monument as found, 🗆 lowe	red monument, 🗆 removed monument (explain)
K	OnApr. 28, 1976placed a Minnesota stamped N.E. Cor. Sec. 2, T115N	Highway Department cast iron monument, R40W.
	EC. 35 IIGN CENTER OF DROP INLET	SEC. 36
	83.25	
	ROAD————————————————————————————————————	
		72.70 II PUNCH HOLE IN SOUTH END OF METAL CULVERT
)	127.00
	1	CENTER OF DROP
	1 .	INLET
		· 1
TII	EN '	.1
	C. 2	SEC. I
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under		OFFICE OF THE REGISTER OF DEEDS County of Yellow Medicine
my direct supervision.		I hereby certify that this document was filed in the Reg. of Deeds office at 9:30 p.M. on the
Totest Closes 5/4/76 SIGNATURE DATE		27 day of A.D., 19 76
Regist	ration No. 11864	Register of Deeds Norman & Opdahl
	Land Surveyor, \square Professional Engineer	By Kay Nerdala, Deputy
1 -	County Surveyor D County Engineer	DOCUMENT NO. 16705

Statement of Evidence: Northeast Cor. Sec. 2, T115N, R40W

- 1858 The original Public Land Survey of township line was completed by W. J. Neeley. A wood post was set and coal was deposited in a mound of dirt with trenches and pits to mark the corner.
- 1901 John Norgaard, the County Surveyor, found a stone in the government mound and set a 6"x6"x24" granite monument in the mound to mark the corner. He used this monument on subsequent surveys in 1913 and 1915.
- 1937 The County Engineer replaced the granite monument with a 6"x6"x24" concrete monument.
- 1976 A Minnesota Highway Department survey crew excavated a hole 4'x4'x 3½' deep. A 6"x6"x24" concrete monument was found 18" below the present road surface. There was nothing under the concrete monument. A Minnesota Highway Department cast iron monument stamped N.E. Gor. Sec. 2, T115N, R40W was placed over the concrete monument and about 3" below the road surface.

An analysis of this data provides a continuous chain of record perpetuating the location of the original Public Land Survey Corner.

For details of survey analysis and 1976 electronic measurements, see the survey report for S.P. 8702 and S.P. 8706, Jct. T.H. 23 and T.H. 67, 3 miles S.W. of Granite Falls, on file with the Surveys Section, Minnesota Highway Department, Willmar, Minn. 56201.