



Statement of Evidence: N $\frac{1}{4}$  Cor. Sec. 12, T115N, R40W.

1864 - The original Public Land Survey was completed by G. E. Davis and J. W. Webb, Jr. A wood post was set in a dirt mound with trenches and pits to mark the corner.

There is no record evidence that anything has been set to mark the corner since the original Public Land Survey.

1915 - John Norgaard, the County Surveyor, surveyed the north line of the section. His survey shows the distance from the northwest section corner to the quarter corner to be 2632 feet and from the quarter corner to the northeast corner of the section to be 2622.5 feet. He said that a stone was set north of the line, but he didn't show how far north of the line.

1976 - A Minnesota Highway Department survey crew excavated a 6'x10'x3 $\frac{1}{2}$ ' deep hole at intersection of the centerline of an east/west township road and a north/south fence line north. Nothing was found to mark the corner.

The excavation was 3 feet west, 7 feet east and 3 feet north and south of the lost location. A Minnesota Highway Department cast iron monument was set at the lost location and 3 inches below the road surface. The monument is stamped N $\frac{1}{4}$  Cor. Sec. 12. The lost location is 2 feet west of the fence line north and one foot north of the centerline of the east/west road.

For details of survey analysis and 1976 electronic measurements, see the survey report for S.P. 8702 and S.P. 8706, Jct. T.H. 23 and T.H. 67, 3 miles S.W. of Granite Falls, on file with the Surveys Section, Minnesota Highway Department, Willmar, Minn. 56201.