CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Section 1	, Township $\frac{115\text{N}}{}$, Range $\frac{40\text{W}}{}$, $\frac{5\text{th}}{}$ P.M.
STATE OF MINNESOTA, County of Yellow Medicine	
At the corner location shown on the sketch:	
On Apr. 29. 1976 found anothing marking the corner.	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
DATE down 2 inches below road surface.	alghway Department cast from monument
SKETCH OF REFERENCE TIES	
COPPER NAIL & DISC IN NORTHEAST SIDE OF POWER POLE 91.02' N. W. (UP 2.0') SECTION CENTER OF HOLE IN TOP OF C.M. P. CULVERT (SOUTH END) 33.55' S.W.	SECTION 6
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Richard Muniforms 9-15-77 SIGNATURE DATE Registration No	OFFICE OF THE YELLOW MEDICINE COUNTY OFFICE OF THE YELLOW MEDICINE COUNTY County of Yellow Medicine I hereby certify that this document was filed in the Reg. of Deeds office at 12:10 PM. on the 4 day of October A.D., 19 77 COUNTY RECORDER YELLOW MEDICINE COUNTY RECORDER YELLOW MEDICINE COUNTY RECORDER YELLOW MEDICINE COUNTY RECORDER
© Land Surveyor, □ Professional Engineer	By Kay Nerdahl Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 170323

Statement of Evidence: E% Cor. Sec. 1, T115N, R40W, 5th P.M.

- 1858 The original Public Land Survey of the township line was completed by W. J. Neeley. A wood post was set over deposited coal in a dirt mound with trenches and pits to mark the corner.
- 1913 John Norgaard, County Surveyor, located the corner midway and on line between section corners. He also did this in 1915 but did not state whether he set anything to mark the corner in either case.
- 1976 The Minnesota Highway Department excavated a 7 foot by 8 foot by 3% foot deep hole to natural ground at the intersection of the centerline of a north/south road with a fence line west. Nothing was found marking the corner.
- 1976 Mn/DOT set a cast iron monument 4 inches below the road surface at the lost location.

The lost location is accepted as the position of the government corner because the County Surveyor set the corner at this position 63 years ago and it also fits the occupation lines, that is, at the intersection of the centerline of a north/south road and a fence line west.

For details of survey analysis and 1976 electronic measurements, see the Survey Report for S.P. 8702 and S.P. 8706, Jct. T.H. 23 and T.H. 67 - 3 miles S.W. of Granite Falls, on file with the Surveys Section, Mn/DOT, Willmar, MN, 56201.