

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 15, Township 114 N., Range 41 W., 5th. P.M.

STATE OF MINNESOTA, County of YELLOW MEDICINE


At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 8-12-87 placed a 1 1/4" x 1 1/4" x 20" PERFORATED STEEL TUBE WITH
DATE
ALUMINUM CAP STAMPED "D.N.R. SURVEY MARKER", DOWN 0.2'

SKETCH OF REFERENCE TIES



NOTE:
 MONUMENT IS
 22' EAST OF ϕ N-S ROAD
 15' NORTH OF ϕ ROAD EAST



BEARINGS OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page.

J.B.M. 8-18-87
A-1105

RECORDED
 GRANTED
 GRANTEE
 INDEXED

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pomeroy Jr. 8-20-87
 SIGNATURE DATE
 Registration No. 17005

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of Yellow Medicine

I hereby certify that this document was filed in the Co. Recorders office at 9:55 A.M. on the 24 day of August A.D., 19 87

County Recorder Norman J. Opdahl

By Kay Nordahl, Deputy

DOCUMENT NO. 191466

East Quarter Corner Section 15, Township 114 North, Range 41 West

The DNR Bureau of Engineering contacted the following offices for corner information:

Secretary of State
Yellow Medicine County Recorder
Yellow Medicine County Highway Engineer

- 1867 U.S. General Land Office notes in the Secretary of State's Office describes this corner as a set post with charred stake, mound and pits.
- 1891 Surveyor's Record Book, on page 104, from the County Recorder's Office, contains a survey by Jonah Peterman, County Surveyor. Survey states a line was "run from East $\frac{1}{4}$ to West $\frac{1}{4}$ post". A stone is shown at this corner, which measures 40.50 chains (2673.00 ft.) from the northeast corner Section 15.
- 1901 Surveyor's Record Book B, on page 33, from the County Recorder's Office, contains a township plat showing distances between government corners obtained from a re-monumentation survey by John Norgaard, County Surveyor. No mention of this corner is made, but a distance of 5306 ft. is shown between adjoining section corners. Adjoining section corners were not found, but re-established by the re-monumentation survey by Norgaard.
- 1987 July 21, the DNR Bureau of Engineering conducted a search for this corner centered on the lost position. The lost position falls 20 ft. east of a north-south road and 6 ft. north of a driveway east, in a mowed lawn area, very well kept. Talked with landowner, Darrel Nikolaisen, approximately 65 years old, who has never seen or heard of a monument in this area, and would not allow any digging here. Scanned a 20 ft. diameter area with an electronic metal locator, but found nothing. Lost position was found to measure 2660.08 ft. from adjoining section corners.

Analysis of the available information led the DNR Bureau of Engineering to conclude that the corner is lost and accepted the lost position for its location.