CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
.	
	ER Corner of Section 22 Township 114 N., Range 41 W., 5th PM. SOTA, County of YELLOW MEDICINE Islan shown on the sketch: Islan shown on the sketch: If monument as found, lowered monument, removed monument (explain) 2-87 placed a 11/4" x 11/4" x 20" PERFORATED STEEL TUBE WITH NEW CAP STAMPED "D.N.R. SURVEY MARKER", UP 0.2" SKETCH OF REFERENCE TIES SPELLMAN LAKE D.N.R. NAIL & DISC SE SIDE 10" BUTTERNUT, UP 4.0" IS HOF WATER'S EDGE BEARINGS OBSERVED WITH COMPASS THOSE WATER'S EDGE DESCRIPTION MEDICINE BEARINGS OBSERVED WITH COMPASS THOSE WATER'S EDGE DESCRIPTION MEDICINE BEARINGS OBSERVED WITH COMPASS GENTLE OF THE COUNTY RECORDER COUNTY RECORDER COUNTY of Yellow Medicine I hereby certify that this document was filed in the Co. Recorders of files at 10:115 A.M. on the Co. Recorders of files at 10:125 A.M. on the Co. Recorders of files at 10:125 A.M. on the Co. Recorders of files at 10:125 A.M. on the Co. Recorder Norman J. Opdahl BY TOWNS THE TIME TOWNS TOW
DATE left monument as found, lowered monument, removed monument (explain) On	
□ On found a	
	Med monument
RATE	
SKETCH OF REFERENCE TIES	
SPELLMAN	LAKE
- No	
Allo 🖚	
EAST SIDE 9" BUTTERNUT, UP 4.0' HLG	
Τ΄ Ω N 46 E Τ΄ Ω 11.55'	
N.O	D.N.R. NAIL & DISC
•••••	
MONUMENT IS	
35.00 SOUTH OF WATER'S EDGE	
BEARINGS OBSERVED WITH COMPASS	
Statement of evidence relative to this corner loc	A-1105 RECORDE
I hereby certify that this document and the data	OFFICE OF THE COUNTY PECOPOED GRANTER
contained herein was prepared by me or under	County of Yellow Medicine
my direct supervision.	the Co. Recorders office of 10:15 A.M. on the
	24 doy of August A.D., 19 87 County Records Norman J. Opdahl
Registration No. 17005 / Professional Engineer	
□ County Surveyor, □ County Engineer	DOCUMENT NO. 191470

Meander Corner #3 of Section 22, Township 114 North, Range 41 West

The DNR Bureau of Engineering contacted the following offices for corner information:

Secretary of State Yellow Medicine County Recorder Yellow Medicine County Highway Engineer

- 1867 U.S. General Land Office notes in the Secretary of State's Office describes this corner as a set post with a 4" by 8" limestone in mound and pits.
- 1987 April, the DNR Bureau of Engineering conducted a search for the corner but found nothing. The corner area has recently been filled in with material that includes numerous large stones. Located the current toe of ice ridge around the lake and intersected it with the east line of Section 22. This gave a distance of 1259.54 ft. from the southeast corner of Section 22, GLO had 1229.58 ft. to this corner.

The DNR Bureau of Engineering considers this corner to be lost and re-established it using lost methods. Lost position measures 1239.09 ft. from the southeast corner of Section 22.