CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
# 6 MEANDER Corner of Section 22 Township 114 N., Range 41 W. 5th. P.M.	
STATE OF MINNESOTA, County of YELLOW MEDICINE	
At the corner location shown on the sketch:	
Onfound a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 8-11-87 placed a 11/4"x11/4"x 20" PERFORATED STEEL TUBE WITH ALUMINUM CAP STAMPED "D.N.R. SURVEY MARKER", UP 0.2"	
SKETCH OF REFERENCE TIES	
D.N.R. NAIL & DISC NE SIDE 8" WILLOW UP 3.2' N70°W. 27.05' D.N.R. NAIL & DISC NE SIDE 8" WILLOW UP 3.2' SPELLMAN LAKE SPELLMAN LAKE N70°W. 27.18' D.N.R. NAIL & DISC NORTH SIDE 10" WILLOW UP 3.0'	
BEARINGS OBSERVED WITH COMPASS	
Statement of evidence relative to this corner location is on back of page. J.B. M. 8-18-87 A-1105 RECORDED	
hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER GRANTEE County of Yellow Medicine GRANTEE
Registration No. 17005	I hereby certify that this document was filed in the Co. Recorders office at 10:30 A.M. on the 24 day of August A.D., 19 87 County Recorder Norman J. Opdahl
■ Land Surveyor, □ Professional Engineer □ County Surveyor, □ County Engineer	DOCUMENT NO. 191473

Meander Corner #6 of Section 22, Township 114 North, Range 41 West

The DNR Bureau of Engineering contacted the following offices for corner information:

Secretary of State Yellow Medicine County Recorder Yellow Medicine County Highway Engineer

- U.S. General Land Office notes in the Secretary of State's Office describes this corner as a set post. Government notes state the north line of Section 22 was run on a true line as adjoining section corner posts could be seen from one point. This meander corner measures 32.50 chains (2145.00 ft.) from the northwest corner of Section 22.
- Surveyor's Record Book, on Page 20, from the County Recorder's Office contains a survey by Jonah Peterman, County Surveyor. Survey shows a distance of 32.85 chains (2168.10 ft.) from the northwest corner of Section 22, east to a lake. No mention of this corner is made.
- 1987 April, the DNR Bureau of Engineering conducted a search for this corner, but found nothing. Located the edge of the lake in the corner area and intersected it with the north line of Section 22. This gave a distance of 2187.7 ft. from the northwest corner of Section 22.

The DNR Bureau of Engineering considers this corner to be lost and re-established it using lost methods. Lost position measures 2170.56 ft. from the northwest corner of Section 22.