CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
#4 MEANDER Corner of Section 24 , Township 113 N. , Range 39 W. , 5th P.M. STATE OF MINNESOTA, County of YELLOW MEDICINE	
At the corner location shown on the sketch:	
On found a	
	ed monument,
On 7/19/89 Placed a 1 1/4"X 1 1/4"X 2	O" PERFORATED STEEL TUBE WITH
ALUMINUM CAP STAMPE	D "DNR SURVEY MARKER", UP 0.3'
SKETCH OF REFERENCE TIES	
	DNR PROPERTY
	MONUMENT
g!	
моте: 1 2 9	
PLACED 3/4"X 24" IRON ROD INSIDE MONUMENT	TIES NOT AVAILABLE
STEEL WINESS POST 1.0' EAST_OF MONUMENT	
REFERENCE	``````````````````````````````````````
MONUMENT	WITNESS
25.60	POST 700 OF
W.C. ₩ .2.W	OF BANK
CURTIS	
LAKE	
····	
7/27/89	
Statement of evidence relative to this corner location is on back of page. G-225	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of Yellow Medicine
my direct supervision.	I hereby certify that this document was filed in
SIGNATURE DATE	the Co. recorders office at 11:30 A.M. on the 4 day of August A.D., 19.89
Registration No. 17005	County Recorder normal and
■ Land Surveyor, □ Professional Engineer □ County Surveyor, □ County Engineer	By,Deputy
County surroyor, Co sounty Engineer	DOCUMENT NO

Meander Corner #4 of Section 24, Township 113 North, Range 39 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State Yellow Medicine County Recorder and Highway Engineer Moseng Land Surveying at Marshall KBM at Redwood Falls

- 1857 The U.S. General Land Office notes in the Secretary of State's Office show the corner is a post, drove charred stake, built mound of earth and dug trench as per instructions.
- 1989 July, the DNR Bureau of Engineering computed the lost position for this corner and found it to measure:

1366.11 ft. from Meander Corner #3 of Section 24
1499.39 ft. from the northeast corner Section 24
Conducted a search for this corner, but found the lost falls in Curtis
Lake.

Analysis of the available information led the DNR Bureau of Engineering to conclude that the lost position marks the location of the corner. Set a reference monument to this corner as shown.