

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 25, Township 113 N., Range 39 W., 5th P.M.

STATE OF MINNESOTA, County of YELLOW MEDICINE


At the corner location shown on the sketch:

On 7/11/89 found a 60d SPIKE, FLUSH  
DATE


left monument as found,  lowered monument,  removed monument (explain)

On 7/11/89 Placed a 1 1/4" X 1 1/4" X 20" PERFORATED STEEL TUBE WITH  
DATE ALUMINUM CAP STAMPED "DNR SURVEY MARKER", DOWN 0.8'

### SKETCH OF REFERENCE TIES



NOTE:  
PLACED 3/4" X 24" IRON ROD  
INSIDE MONUMENT DOWN 0.8'



TIES NOT AVAILABLE

Statement of evidence relative to this corner location is on back of page. 7/26/89  
G-225

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell B. Pommeroy 8-2-89  
SIGNATURE DATE

Registration No. 17005  
 Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
County of Yellow Medicine

I hereby certify that this document was filed in the Co. recorders office at 11:40 A.M. on the 4 day of August A.D., 1989

County Recorder Norman J. Anderson  
By \_\_\_\_\_, Deputy  
DOCUMENT NO. 195724

East Quarter Corner Section 25, Township 113 North, Range 39 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State  
Yellow Medicine County Recorder and Highway Engineer  
Moseng Land Surveying at Marshall  
KBM at Redwood Falls

1857 The U.S. General Land Office notes in the Secretary of State's Office show the corner is a post, drove charred stake, built mound of earth and dug trench as per instructions.

1989 July 11, the DNR Bureau of Engineering hired a backhoe operated by Wyatt Bendix of Echo to dig for evidence of this corner. Found a 60d spike at the intersection of a north-south road and fence line east. Dug a 12 ft. north-south by 6 ft. east-west hole, centered on the found spike, to a depth of 3 ft., but found nothing. According to Mrs. Hughs, 50 year old lifetime resident, the fence has been there all her life. Above mentioned road and fence intersection measures:

2675.57 ft. from the northeast corner Section 36

5079.50 ft. from Meander Corner #3 of Section 24

Also dug at a point 35 ft. south of this road and fence intersection. Dug a 16 ft. north-south by 6 ft. east-west hole, centered on the point 35 ft. south, to a depth of 4 ft., but found nothing.

Analysis of the available information led the DNR Bureau of Engineering to conclude that the above mentioned intersection of road and fence marks the location of the corner. Discarded the found spike and placed a DNR Survey Marker with 3/4" by 24" iron rod inside down 0.8 ft..