# 7 MEANDER Corner of Section 30 Township 115 N Range 38 W 5 th P.M. STATE OF MINNESOTA, County of YELLOW MEDICINE At the corner location shown on the sketch: On DATE found q left monument as found, lowered monument, removed monument (explain) On DATE Placed q lowered monument, removed monument (explain)	
SKETCH OF REFERENCE TIES NOTE: NO MONUMENT SET AREA OF CORNER IS IN THE MINNESOTA RIVER (6-14-95) Statement of evidence relative to this corner location is on back of page.	
Statement of evidence relative to this corner lo	cation is on back of page. JBM OCT '95 SPK.00277.00.00.0
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. SIGNATURE License Number Land Surveyor, Professional Engineer County Surveyor, County Engineer	OFFICE OF THE COUNTY RECORDER County of Yellow Medicine I hereby certify that this document was filed in the Co. recorders office at 10:40 A .M. on the 7 day of November A.D., 19 95 County Recorder A.D., 19 95 County Recorder DOCUMENT NO. 210280

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office Mn/DOT Offices in St. Paul and Willmar Yellow Medicine County Recorder's Office

Yellow Medicine County Highway Engineer's Office

Montevideo City Engineer's Office

Bonnema Surveys of Willmar

Moseng and Zieske Surveying, Inc. of Marshall

Michael Nyberg, RLS #13145, of Carlos

West Central Land Services, Inc. of Willmar

K.B. MacKichan and Associates, Inc. of Redwood Falls

- 1864 U.S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a mound of earth with pits on the right bank of the Minnesota River. The corner is shown:
 - 31.00 chains (2046.00 feet) from the north quarter corner of Section 30. The notes show that a distance east of corner was not measured.
- 1866 U.S. General Land Office notes for the subdivision of Township 115 North, Range 38 West that lies north of the Minnesota River, obtained from the Secretary of State's Office show that the wood post that was set in 1864 was found at corner. The corner is shown:

North 62° West, 4.87 chains (321.42 feet) from Meander Corner Number 4

1977 May, a subdivision of Section 30 shown on Certificate of Surveys in the northeast quarter of Section 30 and in the east half of Section 19 obtained from West Central Land Services, Inc. shows that an iron pipe was set for the northeast corner of Section 30. A distance of 2652.67 feet is shown between the north quarter corner of Section 30 to the northeast corner of Section 30 no information is given about Meander Corner Number 7.

A note on a copy of a subdivision of Section 30 obtained from West Central Land Services states that the northeast corner was established at a theoretical position.

- 1995 June, DNR Bureau of Engineering computed a position for the meander corner as follows:
 - A) 2046.00 feet (GLO distance) from the north quarter corner of Section 30
 - B) on the easterly extension of a line from the northwest corner of Section 30 thru the north quarter corner of Section 30

Do not accept the procedure used in 1977 to establish the north line of Section 30 in the area of meander corner because it was computed from a theoretical position for the northeast corner of Section 30 (GLO did not set the northeast corner of Section 30 in 1864).

Analysis of the above information led the DNR Bureau of Engineering to conclude that the computed position for corner - GLO distance from the north quarter corner of Section 30 and on the easterly extension of a line from the northwest corner of Section 30 thru the north quarter corner of Section 30 - marks the location of corner. Did not set a monument to mark corner or a reference monument to it because area of corner is in the flood plain of the Minnesota River.

