CERTIFICATE OF LOCATION OF GOVERNMENT CORNER NORTHEAST
At the corner location shown on the sketch:
On Feb. 23, 1998 found a found iron set by County Highway Department. (see back)
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)
On Feb. 23, 1998 placed a 5/8" iron with seal No. 11943 over found iron.
SKETCH OF REFERENCE TIES
Nail & seal in corner fence post - SE 125.45' Noil & seal in corner fence post - SSE 134.75 Top of telephone pedestal - NW 69.77' RECORDED GRANTER / GRANTER / GRANTER / GRANTER / HIGHERED
Statement of evidence relative to this corner location is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Act County of
□ Land Surveyor, □ Professional Engineer □ County Surveyor, □ County Engineer □ DOCUMENT NO. 217851

STATEMENT OF EVIDENCE

美国的军事态

THE COUNTY HIGHWAY DEPARTMENT RECORDED IN THEIR NOTES THAT THE CORNER WAS FOUND AND USED IN 1952 WHEN THE ROAD WAS RE-GRADED. THE CORNER WAS FOUND AGAIN IN 1962 AND 1964 BY THE COUNTY HIGHWAY DEPT.

ON FEBRUARY 23, 1998, MOSENG LAND SURVEYING FOUND AN IRON SET BY THE COUNTY HIGHWAY DEPARTMENT. THE TIES PROVIDED BY THE HIGHWAY DEPARTMENT WERE DESTROYED. WE SET A 5/8" IRON WITH SEAL NO. 11943 OVER THE FOUND IRON.