CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
NORTH QUARTER Corner of Section 26 , Township 115 N. , Range 44 W. , 5th P.M.
STATE OF MINNESOTA, County of
At the corner location shown on the sketch:
□ On found a
DATE left monument as found, lowered monument, removed monument (explain)
On 5/2/2000 Placed a 3/4" X 24" REBAR WITH A PLASTIC CAP STAMPED "MN DNR LS 17003"
DATE
SKETCH OF REFERENCE TIES
£ FIELD APPROACH
88'
-
Q _{.::} 2.5
7.5'
×
YELLOW MEDICINE COUNTY
NAD 83 (1996 ADJ.)
E = 441759.261 Statement of evidence relative to this corner location is on back of page. 6/13/2000 WMA00267
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER County of Yellow Medicine
my firect supervision
Co. Recorder's Office at 10:15 A.M. on the SIGNATURE 5 day of
License Number
□ County Surveyor, □ County Engineer

North Quarter Corner of Section 26, Township 115 North, Range 44 West

The DNR Bureau of Engineering contacted the following for survey information:
Minnesota Secretary of State's Office

Yellow Medicine County Recorder's Office
Yellow Medicine County Highway Engineer's Office

Montevideo City Engineer's Office

- 1871 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a raised mound as per instructions.
- October, page 251 of a Surveyor's Record Book, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Survey states that corner was established on line and equal distance between section corners. A pole was set to mark corner and is shown:

 2640 feet from adjoining section corners
- 2000 May 2, DNR Bureau of Engineering hired a backhoe to dig for evidence of the corner. A 6 foot north-south by 16 foot east-west by 4 foot deep hole was dug, the center being on the centerline of an east-west Township Road and 6 feet east of a fence south. No evidence of a monument was found in excavation. Computed the lost position for corner and found it to be:
 - A) 2.5 feet north of the centerline of an east-west Township Road
 - B) 7.5 feet east of a fence south which bends westerly at its northerly end but lines up with the straight portion about 500 to 1000 feet south
 - C) 2638.74 feet from adjoining section corners

Analysis of the above information led the DNR Bureau of Engineering to conclude that the lost position marks the location of the corner. Set a 3/4" by 24" rebar with plastic cap stamped "MN DNR LS 17003" at the computed lost position for corner.