

East Quarter Corner of Section 22, Township 115 North, Range 44 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office
Yellow Medicine County Recorder's Office
Yellow Medicine County Highway Engineer's Office
Montevideo City Engineer's Office

- 1871 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a raised mound as per instructions.
- 1911 October, page 251 of a Surveyor's Record Book, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Survey states that corner was established on line and equal distance between section corners. A monument was not set to mark corner but it is shown:
2646 feet from adjoining section corners
- 2000 May 2, DNR Bureau of Engineering computed the lost position for corner and found it to be:
2646.35 feet from adjoining section corners
Conducted a field search at the computed lost position for corner but no evidence of a monument was found. The computed lost position for corner was also found to be:
in line with fences east and west
21.5 feet west of the center line of a Township Road
on the slope of road

Analysis of the above information led the DNR Bureau of Engineering to conclude that the lost position marks the location of the corner. Set a 3/4" by 24" rebar with plastic cap stamped "MN DNR LS 17003" at the computed lost position for corner.