CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
EAST QUARTER Corner of Section 33 , Township 114 N. , Range 46 W. , 5th P.M.	
STATE OF MINNESOTA, County ofYELLOW MEDICINE	
At the corner location shown on the sketch:	
On 10/11/2000 found a 16" DIA. FIELD STONE, FLUSH WITH OLD ROAD SURFACE.	
■ left monument as found, □ lowered monument, □ removed monument (explain)	
On 10/11/2000 Placed a 3/4" X 12" REBAR ON THE SOUTH SIDE OF	
THE STONE, DOWN 0.2'.	
SKETCH OF REFERENCE TIES	
N (28)	127 ×
733	
_	
3, 60, 3, 60,	1 <u>4</u>
PRAIRIE 1800	CULTWATED FIELD
Z	durin.
60HD 13	POND
80° I.≱ 80,7 70,7 81,7 82,7 83,7 83,7 83,7 83,7 83,7 83,7 83,7 83	2641.40
BEARINGS ARE YELLOW 8	264
MEDICINE COUNTY ORIENTATION, NAD83, 1986 ADJ.	
YELLOW MEDICINE COUNTY	R
COORDINATES, NAD 83 1986 ADJ. N = 135637,472	CORNER IS ON © OF OLD,  WASHED OUT TWP ROAD  NO TIES AVAILABLE
E = 370101.012	II)
Statement of evidence relative to this corner lo	cation is on back of page.
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under  my direct supervisib.	County of Yellow Medicine
Muce W. Milled 6/4/01	I hereby certify that this document was filed in the Co. Recorder's Office at 9:50 A.M. on the
SIGNATURE // DATE License Number17003	13 day of <u>June</u> A.D., 20 <u>01</u>
■ Land Surveyor, □ Professional Engineer	County Recorder Kay Nerdahl  By Sau Rohik  DOCUMENT NO 226148 eputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.

## East Quarter Corner of Section 33, Township 114 North, Range 46 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office

Yellow Medicine County Recorder's Office

Yellow Medicine County Highway Engineer's Office

- 1871 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a raised mound as per instructions.
- A page in a Surveyor's Record Book, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Survey shows corner but does not indicate what kind of monument was found or set. The corner is shown:

2643 feet from the northeast corner of Section 33

2637 feet from the southeast corner of Section 33

2000 October 10, DNR Bureau of Engineering traversed to the area of corner and found a 16 inch diameter field stone flush with the ground on the center line of an old washed out road. Searched the area for other stones but did find any. The stone was found to be:

2643.04 feet from the northeast corner of Section 33

2641.39 feet from the southeast corner of Section 33

11.27 feet east of a straight line between adjoining section corners

0.90 of a foot south and 11.27 feet east of the lost position per GLO survey

2.10 feet north and 11.29 feet east of the lost position per 1913 survey

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found 16 inch diameter field stone marks the location of the corner. To aid in finding the stone in the future a 3/4 inch by 12 inch rebar was set down 0.2 of a foot on its south side.