Doc# 248624 Fee: \$0.00 2 Pages

Office of County Recorder Yellow Medicine County, Minnesota I hereby certify that the within instrument was filed on July 23, 2009 at 10:25 AM

N/C Daniel G. Nickols, PLS Minnesota Dept. of Natural Resources 500 Lafayette Road St. Paul, MN 55155-4037 By Laile Datkoun Deputy

Index No. L-13
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
EAST_QUARTER Corner of Section 16 ,Township 114 ,Ronge 44
5 Principal Meridian, State of Minnesota, County ofYELLOW MEDICINE
At the corner location shown on the sketch:
□ On found a
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain
☑ On 5/19/09 Placed a 3/4"X 12" REBAR WITH CAP STAMPED "MN DNR LS 1983
SET FLUSH, MIDWAY AND ON LINE BETWEEN NE & SE CORNERS
N-
F 500 H
S W A L E
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
The G. Months
YELLOW MEDICINECOUNTY COORDINATE SYSTEM NAD 1983 1996 ADJ. N = 151158.209 E = 433824.183 NO TIES AVAILABLE
The state of the s
REGISTERED \
YELLOW MEDICINECOUNTY COORDINATE SYSTEM SURVEYOR 19839
NAD 1983 1996 ADJ.
N = 151158.209 E = 433824.183 NO TIES AVAILABLE
Statement of guidance for this passed leaving in an healt of this passed 07/06/09
I certify that this document was researched and prepared by me or under my direct supervision. SIGNATURE DATE MARCH 25, 2009 License Number 19839
Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence for the East Quarter Corner of Section 16, Township 114 North, Range 44 West of the 5th Principal Meridian.

1871

The subject corner was established by L. Harrington. His notes state that he ran north on true line between Sections 15 & 16. At 0.50 Chains he intersected a dry creek, 5 links wide; At 40.00 Chains he set a post for 1/4 Section Corner;

At 41.00 Chains he intersected a dry creek, 5 links wide;

At 60.00 Chains same creek;

At 80.00 chains Set a post in raised mound for the corner to Sections 9,

10, 15 & 16. (No ties taken).

Neither Mr. Harrington's monument nor accessories were found during our survey.

2009

Field Crew from Minnesota Department of Natural Resources (DNR) was unable to find any monument at this location. An excavation was not undertaken as this is an area of substantial fill due to the proximity of low land and there being no historic monuments in the record after the original survey. The corner was determined to be lost and was established midway and on line between the NE & SE corners of Section 16.

For more information concerning this survey contact Minnesota Department of Natural Resources.