CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
SE Corner of Section 30 , Township 116 , Range 39 , 5TH P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
☑ On 1-4-2012 found a 5/8" REBAR 0.4' BELOW DIRT IN A FIELD	
☑ left monument as found, □ lowered monument, □ removed monument (explain)	
□ On placed a	
SKETCH OF REFERENCE TIES  E 1 COR FD. REBAR	
SECTION 30	W/CAP #19092
T116N - R39W FARMPLACE	N SECTION OF
- FARIMIPLACE	SECTION 29
	— — — — — — — — — — — — — — — — — — —
	SECTION 29 T116N - R39W
ASPHALT INT. OF CL ROAD	FOUND TREBAR Z STOR
SI COR.	NE 0.4' BELOW DIRT FD. ½" PIPE
FD. SURVEY NAIL S 88°50'32"E 2658.02'.	N 89°51'35"E 2652.26'
290th Ave	
FIELD	
	<del>-</del> 4
	5'53"E 2639.44
OF OF ION OF	3.6 2
. SECTION 31	SECTION 32
T116N - R39W	2 T116N - R39W
12	111014-110314
SECTION 31 T116N - R39W  SECTION 32 T116N - R39W  W 1 COR FD. 1" PIPE	
WIN STATE FEATE GOOTH GOOTH MAD GOOD.	
N:995164.58 E:2213339.88	
Statement of evidence relative to this corner location is on back of page.	
Statement of evidence relative to this come receipt to the section	
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under	County of
my direct supervision.	I hereby certify that this document was filed in
GNATURE 1/4/2012	the Co. Recorders office atM. on the day of A.D., 20
	·
Registration No. 48998	By, Deputy
□ Land Surveyor, □ Professional Engineer     □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	DOCUMENT NO
☐ County Surveyor, ☐ County Engineer	

î.

## STATEMENT OF EVIDENCE

The Southeast Corner of Section 30, Township 116 North, Range 39 West of the 5th Principal Meridian.

U.S. General Land Office notes show corner marked a wood post in a mound with pits as per instructions. (1865)

In 1865, W.J. Neely established the lines of this township, as per the information on the copy of the original Township Plat as provided by the Register of Deeds. No other information exists was able to be found. Original notes were unable to be found.

On 1-4-12, a survey crew from Ulteig Engineers found and accepted a grant Rebar, and set new ties as shown. Monument was accepted in a non-filed survey by Roy Marihart. Since no public record is available for this monument, it is the opinion of Ulteig Engineers that the location of this monument correctly perpetuates the position of the original corner based upon local use and occupation, as well as corroborative evidence in the form of distances to adjacent corners.

Uteig Engineers contacted the following for survey information:

Yellow Medicine County Recorder's Office
Yellow Medicine County Highway Engineer's Office
Chippewa County Recorder's Office
Chippewa County Highway Engineer's Office
Marihart Land Surveying
K.B. MacKichan and Associates, Inc.
Bonnema Surveys of Willmar
West Central Land Services, Inc. of Willmar

N/C Ultrig 5701 S. Corporate Place Sioux Falls, SD 57108

> Doc# 254402 Fee: \$0.00 2 Pages Property & Public Services

Property & Public Services
Property Records Division
Yellow Medicine County, Minnesota
I hereby certify that the within instrument
was filed on January 13, 2012 at 9:45 AM

Janel Timm, Yellow Medicine County Recorder

Jehn Blood Deput