Doc# 257658 Fee: \$0.00 2 Pages

Property & Public Services
Property Records Division
Yellow Medicine County, Minnesota
I hereby certify that the within instrument
was filed on May 7, 2013 at 10:35 AM

Janel Timm, Yellow Medicine County Recorder

By Dolera Blood Deputy

N/C BONNEMA SURVEYS INC PROFESSIONAL LAND SURVEYING 1809 22ND STREET SW SUITE 104 WILLMAR MN 56201

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Sec	ction 24 , Township 114 , Range 45
Fifth Principal Meridian, State of Minnesota, County of Yellow Medicine	
At the corner location shown on the sketch:	
X On Dec. 6, 2012 found nothing	
left monument as found	owered monument removed monument (explain)
X On <u>Dec. 6, 2012</u> placed a <u>Cast Iron Ca</u>	pped 2" x 30" Telspar monument midway and online between
the NE and SE corners of this section	
Nail & Disk of top Wood Fer post 0.60' NV	ncel V
Section 24 Nail & Disc on Wood Fence Post 74.67' West	Nail & Disc on Wood Fence Post 88.37' East
[Fileship]	Pastore
Yellow Medicine County Coordinates (1996 Adjustment) N= 146082.06 E= 417895.54	T Survey Washer on Steel Fence Post 75.08' South MnDot Project Coordinates (Lyon County Coordinates 1996 Adjustment) N= 272323.04 E= 404885.17
Statement of evidence for this corner location is on back of this page.	
I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota.	
Signature MMM ank Date 5/3/B	Typed or Printed Name: Matthew D. Runke Reg. No. 46171
Date	reg. no

STATEMENT OF EVIDENCE

East Quarter Corner Section 24, T114N-R45W

1858

W.J. Neely was contracted by the United States Government Land Office to perform the Original Public Land Survey in this township. He records in his field notes "Set cor sec post deposited coal made mound Trench \$ pits as per instruction".

December 6, 2012 Matthew D. Runke, LS 46171, while doing a re-monumentation survey for the Minnesota Department of Transportation, searched an area extending 6.0' north and 6.0' south, 10.0' east and 10.0' west of a straight split location with a metal locator and found nothing. This corner was not excavated due to the 154 year gap in survey activity, records and perpetuation of this corner position. The straight line and split location fits very well with fences running East, South and west of this corner position, and appears to be the best evidence of the location of this section corner. A Cast Iron capped 2"x30" Telspar Monument was placed midway and on line between the northeast and southeast corners of this section.