Doc# 259994 Fee: \$0.00 2 Pages

Property & Public Services
Property Records Division
Yellow Medicine County, Minnesota
I hereby certify that the within instrument
was filed on May 12, 2014 at 9:50 AM

Janel Timm, Yellow Medicine County Recorder

By Kelly Kunger Deputy

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
South Quarter Corner of Section	31 , Township 117 , Range 40
Fifth Principal Meridian, State of Minnesota, County of Yellow Medicine	
At the corner location shown on the sketch:	
On April 11, 2014 found a Nothing	
☐ left monument as found ☐ lowered	monument removed monument (explain)
On April 22, 2014 placed a Iron Rod with a "46169 46171" stamped plastic cap	
Section TII7N-I	
Fence Line	Tilled Field
S 89°43'03" W	N 89°43'03" E 2668.22
SW Corner Township	Jection 31
Section 31 T117N-R40W (Railroad Spike)  Tilled Field	NW Corner
Section I TII6N-R4IW	Section 6   TII6N-R40W
Statement of evidence for this corner location is on back of this page.	
I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota.	
Signature	Typed or Printed Name: Joshua M. Stern
Date	Reg. No. 46169

## STATEMENT OF EVIDENCE

## South Quarter Corner Section 31, T117N-R40W

1858

W.J. Neely was contracted by the United States Government Land Office to perform the Original Public Land Survey of the south line of this township. Neely records in his field notes that he "Set Post deposited coal made mound trench and pits"

1895

Jonah Peterman, County Surveyor, records in the County Surveyor's Record Book, page 114, "Set 1/4 post" and dimensions to section corners East, West and North.

April 22, 2014

Joshua M. Stern, LS 46169, searched a large area with a metal locator and was unable to recover any monument. An Iron Rod with a "46169 46171" stamped plastic cap was set at a position determined using a single proportionate measurement of the 1895 record distances between the Southwest and Southeast corners of this section. This position matches a fence line north and fits center line of road east and west. No large excavation was done for this corner because it falls within the road right of way and no monument has been recorded since 1895.