Doc# 259996 Fee: \$0.00 2 Pages

Property & Public Services
Property Records Division
Yellow Medicine County, Minnesota
I hereby certify that the within instrument
was filed on May 12, 2014 at 10:00 AM

Any alterations were made prior to submission to County Recorder

Janel Timm, Yellow Medicine County Recorder

By Kuly Kuger Deputy

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Southeast 31 117 40 Corner of Section Township , Range Fifth **Yellow Medicine** Principal Meridian, State of Minnesota, County of At the corner location shown on the sketch: On April 10, 2014 found a Nothing DATE left monument as found lowered monument removed monument (explain) On April 22, 2014 placed a Iron Rod with a "46169 46171" stamped plastic cap X E1/4 Corner Section 32 Section 31 Section 31 TI 17N-R40W TII7N-R40W T117N-R40W (46169 46171 Capped Iron) ownship Tilled Field 2640.00 0°04'20" Edge of Road S 89°35'29" E N 89°24'15" E 2640.35 2640.35 SE Corner Township Road S1/4 Corner Section 32 Edge of Road Section 32 T117N-R40W T117N-R40W (Cast Iron Monument) (Nail) Tilled Field Section 6 T116N-R40W Statement of evidence for this corner location is on back of this page. I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota. Joshua M. Stern Signature Typed or Printed Name: 46169 Date

STATEMENT OF EVIDENCE

Southeast Quarter Corner Section 31, T117N-R40W

1858

W.J. Neely was contracted by the United States Government Land Office to perform the Original Public Land Survey of the south line of this township. Neely records in his field notes that he "deposited coal made mound trench and pits"

1895

Jonah Peterson, County Surveyor, records in County Surveyor's Record Book, page 114, dimensions from this corner to the north and west but does not mention what type of monument was found.

April 22, 2014

Joshua M. Stern, LS 46169, searched a large area with a metal locator and was unable to recover any monument. Section corners monuments were found at the Southeast and South Quarter corners of Section 32, along with a monument at the Southwest corner of Section 31. We computed this corner position using proportionate measurement along the south line of Section 32, between the Southeast corner and South Quarter corner of Section 32, according to the 1858 Government survey. An Iron Rod with a "46169 46171" stamped plastic cap was set at this corner position. This proportionate position was verified by the 1895 survey distances along the south line of Section 31. This computed corner position fits well with road center lines east, west, and north, along with use on Quarter and Sixteenth lines in both Sections 31&32. No large excavation was done for this corner because it falls within the road right of way and no record of a monument has been recorded since 1895.