Doc# 261583 Fee: \$0.00 2 Pages

Property & Public Services
Property Records Division
Yellow Medicine County, Minnesota
I hereby certify that the within instrument
was filed on February 26, 2015 at 10:25 AM

Janel Timm, Yellow Medicine County Recorder

By Kelly Kunger Deputy

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section	35 , Township 115 , Range 39
Fifth_ Principal Meridian, State of Minnesota, County ofYellow Medicine	
At the corner location shown on the sketch:	
X On <u>Jan. 28, 2015</u> found a <u>Nothing</u>	
	d monument
On Jan. 30, 2015 placed a Iron Rod with a "46169 46171" stamped plastic cap	
G 4° 92	● Steel Fence Post
Section 26	Section 25
-N- Tilled Field	Jilled Field
ļ ļ	x
ce Post	Fence L _x Fence L _y
Steel Fence Post	
Fence Line	Tree Line
	Nail with Disc on
	18" Twin Elm Trees
et l	41
Jilled Field	Tilled Field
Section 35	Section 36
Statement of evidence for this corner location is on back of this page.	
I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision	
and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota.	
Signature	Typed or Printed Name: Joshua M. Stern
Date2/18/15	Reg. No. 46169

STATEMENT OF EVIDENCE

Northeast Corner Section 35, T115N-R39W

Chas E. Davis & J. W. Webb was contracted by the United States Government Land Office to perform the Original Public Land Survey in this township. Davis & Webb records in their field notes that they "Set post in mound with pits for Corner of Sec's 25, 26, 35 & 36"

John Nygaard, County Surveyor, records in County Surveyor's Record Book, page 373 does not mention what type of monument was found but he does dimension to this corner position.

1914

John Nygaard, County Surveyor, records in County Surveyor's Record Book, page 335 does not mention what type of monument was found but he does dimension to this corner position. Nygaard records a dimension of 2628 from the East Quarter of Section 26 to the Southeast corner of Section 26, but field measurements taken by Bonnema Surveys and his statement on the North Quarter of Section 35 show this measurement should actually be 2658.

Jan. 30, 2015 Joshua M. Stern, LS 46169, searched with a metal locator at this corner position and found no evidence of a section corner monumentation. Stern positioned this corner using 5212 feet east of the Northwest corner of Section 35 (per Nygaard), 2658 feet south of East Quarter of Section 26 (per Nygaard), and 1344 feet west of a fence line near the Southeast corner of the Southwest Quarter of the Southwest Quarter of Section 25 (per Nygaard). This position fits the fence lines well near this corner and fits other use lines in Section 25,26,35, and 36. An Iron Rod with a "46169 46171" stamped plastic cap was set at this corner position.