X Land Surveyor

☐ County Surveyor

Professional Engineer

☐ County Engineer

STATEMENT OF EVIDENCE:

NORTHEAST OF SECTION 34, T115N, R46W, 5TH PM

1871 Corner was originally established by the U.S. General Land Office as a post set in raised mound.

Undated Resurvey completed in which a Government stake and mound were found and set top of monument level with ground.

2017-10-17 Westwood PS received coordinates for this corner location from the County Highway Department.

2017-11-02 Westwood PS searched the area and found a spike which matches the coordinates from the County Highway Department and fits close to the centerline intersection. Accepting as the corner location and replaced with rebar and cap LS 45874 and set 3 reference ties.