Corners to be Indexed N1/4 COR. SEC. 36-115-41 SW COR. SEC. 36-115-41 NE COR. SEC. 2-114-41 Doc# 277300 Fee: \$0.00 2 Pages Property & Public Services \$1/4 COR. SEC. 36-115-41 **Property Records Division** N1/4 COR. SEC. 1-114-41 Yellow Medicine County, Minnesota SE COR. SEC. 36-115-41 I hereby certify that the within instrument NE COR. SEC. 1-114-41 was filed on February 1, 2022 at 9:20 AM I hereby certify that this document and the data Janel Timm, Yellow Medicine County Recorder contained herein was prepared by me or under my direct supervision Deputy 2022 Daniel L. Bueltel 43844 License No. CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Land survey monuments situated in Section 36, Township 115, Range 41, 5TH P.M. STATE OF MINNESOTA, County of YELLOW MEDICINE SECTION 30-115-40 SECTION 25-115-41 SECTION 26-115-41 N: 169464.375 E: 545046.475 5/8" IRON W/SEAL #11943 N: 169457.992 E: 542395.971 N: 169397.318 E: 539746.125 2650.51' 2650.54 N 89'51'43" E N 88'41'18" E ш 3 00.04'18" 00.35'16" SECTION 35-115-41 36-175-47 SECTION 31-115-40 S z N: 166762.488 E: 539773.160 CAPPED 5/8" IRON N: 166780.633 E: 545049.826 5/8" IRON SECTION W/SEAL #19093 FOUND MONUMENT ш 00.31'43" SET MONUMENT 00.04,44" 2635.43 S N 89°41'04" W N 89'41'04" W N: 164112.702 2628.07 E: 542425.497 N: 164127.175 E: 539797.470 2628.07 N: 164098.229 SECTION 6-114-40 E: 545053.524 CAST IRON MONUMENT OVER 6"x6"x18" QUARRIED SECTION 31-114-41 SECTION 31-115-41 STONE Yellow Medicine County Coordinate System (1996 Adj.)

Statement of Evidence: SECTION 36-115-41

N1/4 COR. SEC. 36-115-41

On January 27, 2014 Roy Marihart set 5/8" iron with seal #19092 in centerline of road and midway between section corners.

On July 30, 2021 Bueltel-Moseng Land Surveying did not find iron set by Roy Marihart. Reset corner using Mariharts survey from 2014.

SW COR. SEC. 36-115-41 (NE COR. 2-114-41)

On July 30, 2021 Bueltel-Moseng Land Surveying dug with backhoe and found a 6"x6"x18" quarried stone and set a cast iron monument over top of the stone.

S1/4 COR. SEC. 36-115-41 (N1/4 COR. 1-114-41)

On July 30, 2021 Bueltel-Moseng Land Surveying set a 5/8" iron with seal #43844 midway and on line between section corners, corner fell 1'± south of the centerline of the road.

SE COR. SEC. 36-115-41 (NE COR. 1-114-41)

On July 30, 2021 Bueltel-Moseng Land Surveying found a brigde spike, removed and dug with a backhoe, found nothing. Replaced bridge spike with 5/8" iron with seal #43844.