CERTIFICATE OF LOCATION OF GOVERNMENT CORNER North Quarter Corner of Section 9, Township 115N, Range 39W, 5th P.M.	
STATE OF MINNESOTA, County of Yellow Medicine	
At the corner location shown on the sketch:	
\square On $\frac{9/11/73}{\text{DATE}}$ found a <u>nothing found</u>	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On May 1, 1974 placed a Minnesota Highway Department cast iron monument 18" below ground	
18" below ground	
SKETCH OF REFERENCE TIES	
1 4	
SECTION 4	
CULTIVATE	D
COPPER NAIL & DISC (SOUTH SIDE UP 3.5')	IN TELE. POLE
105.54	_
22.5	
_ C TWP.RD	i -, -
GRAVEL SURFACE	
50.69' 59.90'	
CORRED MAIL O DICCIN CORRED MAIL O DICCIN	
COPPER NAIL & DISC IN TOPPER NAIL & DISC IN CORNER FE.P.(EAST SIDE UP 3.5') POWER POLE (N.E. SIDE UP 2.0')	
SECTION 9	
CULTIVATED	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS County of Yellow Medicine
contained herein was prepared by me or under my direct supervision.	I hereby certify that this document was filed in
Jesse E. Fant 6/3/74/ SIGNATURE DATE	the Reg. of Deeds office at 3:15 PM. on the 18 day of A.D., 19 74
Registration No. 3230	Register of Deeds Norman J. Opdahl
Land Surveyor, 🗗 Professional Engineer	By <u>Kay Nerdahl</u> Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.

M.H.D. FORM NO. 2105

Statement of Evidence: NORTH QUARTER CORNER SECTION 9, T115N, R39W, 5th P.M.

The Public Land Survey was completed by C.E. Davis and J.W. Webb, Jr. in 1864. A wood post was set in a mound of dirt with pits to mark the corner.

John Norgaard, County Surveyor, set a stone in the government mound in 1897 and recovered this stone for a 1909 survey. There is no record evidence that this stone has been found or used since 1909. Norgaard showed the position of the corner to be 61 feet east of being midway between section corners; that is, 2642 feet east of the northwest corner of the section.

An east-west township road is inplace, the centerline of which is 22.5 feet south of the northwest corner of the section. E. Hinz, the landowner south of the township road, stated that the road was built fully on his property and that the section line is north of the township road. South of the road, there is a small fence corner inplace. Hinz stated that he and another farmer placed this fence corner by chaining a distance of 2640 feet east from the centerline of a north-south county road. The 1973 electronic distance from the northwest section corner to the fence corner is 2646.98 feet. Hinz also said he has never seen a stone at the quarter corner.

On September 11, 1973 a Minnesota Highway Department survey crew excavated for this corner. The excavation was started at a point 49 feet north of the fence corner (22.5 feet north of the centerline of the township road). The excavation extended 3 feet east, 9 feet west, 4 feet south and 4 feet north of that point to a depth of 3.5 feet. No evidence of the corner was found in the excavation.

The corner was set by a derivative method proportioning Norgaard's 1909 survey, on line with an east-west fence line to the east which continues to the northeast section corner, and 22.5 feet north of the centerline of the east-west township road. This position is 61.4 feet east and 19.9 feet north of the lost location.

For details of survey analysis, photographs taken during excavation, and 1973 electronic survey measurements, see Survey Report for S.P. 8701 from the Yellow Medicine River to Granite Falls on file in the Surveys Section, Minnesota Highway Department, Willmar, Minnesota.