

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 10, Township 114 N., Range 41 W., 5th P.M.
 STATE OF MINNESOTA, County of YELLOW MEDICINE


At the corner location shown on the sketch:

- On 7-21-87 found a 5/8" x 24" CAPPED REBAR STAMPED "MARK HIJD
AERIAL", ^{DATE} DOWN 0.3'
 - left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



NOTE:
 MONUMENT IS
 ON ϕ N - S ROAD
 1' SOUTH OF ϕ E - W ROAD
 NO TIES AVAILABLE



Statement of evidence relative to this corner location is on back of page.

J.R.M. 8-4-87
 A-1105

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pomeroy 8-20-87
SIGNATURE DATE

Registration No. 17005
 Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
 County of Yellow Medicine

I hereby certify that this document was filed in the Co. Recorders office at 9:45 A.M. on the 24 day of August A.D., 19 87

County Recorder Norman J. Opdahl

By Kay Nerdahl, Deputy

DOCUMENT NO. 191464

RECORDED
 OR
 GRANTEE
 INDEXED

Northeast Corner Section 10, Township 114 North, Range 41 West

The DNR Bureau of Engineering contacted the following offices for corner information:

Secretary of State
Yellow Medicine County Recorder
Yellow Medicine County Highway Engineer

1867 U.S. General Land Office notes in the Secretary of State's Office describes this corner as a set post with charred stake, mound and pits.

1891 Surveyor's Record Book, on page 104, from the County Recorder's Office, contains a survey by Jonah Peterman, County Surveyor. Survey states all of the government corners in Section 10 were found. No mention is made about anything being set to perpetuate their location.

1901 Surveyor's Record Book B, on page 163, from the County Recorder's Office, contains a collection of what was found at government section corners by John Norgaard, County Surveyor, in a township re-monumentation survey. Norgaard states this corner was a found stake in the government mound. A 6" by 6" by 24" jasper granite stone was set at this location, its top level with the ground, Page 33 of Surveyor's Record Book B is a township plat showing distances between government corners obtained from Norgaard's re-monumentation survey. This corner is shown 5306 feet from the northeast corner of Section 15.

No A tie page of field notes from the County Highway Engineer's Office, shows
Date four ties to this corner. A note is made to a field stone being in place.

1987 April 14, the DNR Bureau of Engineering found a 5/8" diameter rebar, capped and stamped "Mark Hurd Aerial". Monument is 1 ft. south of centerline east-west road and on centerline north-south road. Contacted Mark Hurd Aerial Surveys for information on this corner. A Contractor for Mark Hurd stated this monument was set at occupation only, no search was made for the corner. July 21, the DNR Bureau of Engineering hired a backhoe operated by Peterson Excavating of Clarkfield to dig for evidence of this corner. Dug a 10 ft. north-south by 12 ft. east-west hole, the center being at the intersection of the above mentioned roads. Found many large field stones between surface of road and natural ground down 36". Average size of stones was 10" by 10" by 10" no markings were found on any of them. Continued excavation down to 54" but found nothing else, replaced all stones found along with Mark Hurd monument. Searched for, but did not find any record ties. Mark Hurd monument measures 5300.36 feet to the northeast corner of Section 15.

Analysis of the available information led the DNR Bureau of Engineering to conclude that the Mark Hurd monument marks the obliterated position of the corner. None of the found field stones could be identified as the corner.