CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 22 Township 114 N., Range 41 W., 5th P.M.	
STATE OF MINNESOTA, County of YELLOW MEDICINE	
At the corner location shown on the sketch:	
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Onplaced a	
SKETCH OF REFERENCE TIES	
4	E 1/4 CORNER  SECTION 15
  -	
	2660.08
0 00	266
z	—NE CORNER
MC <sup>#</sup> 6 Section 22	SECTION 22
N 89°38'29"E	N 89°22'05"E 2671.57 N 1/4 CORNER
	SECTION 23
<b>*</b>	NOTE: NO MONUMENT SET
54,41 "W	ACCESS TO CORNER
75 8	DENIED BY LANDOWNER
O Z	
	MC#3 Section 22
BEARINGS ARE ASSUMED ORIENTATION	
Statement of evidence relative to this corner loc	cation is an back of agge   LRP 8-19-87
	GRANTE
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER INDEXED
my direct supervision.	I hereby certify that this document was filed in
Levell R. Pourereury & 8-20-87	the Co. Recorders office at 10:10 A.M. on the 24 day of August A.D., 19 87
Registration No. 17005	County Recorder Norman J. Opdahl
M Land Surveyor, D Professional Engineer	By Kay Nerdall Deputy
□ County Surveyor, □ County Engineer	DOCUMENT NO.

Northeast Corner Section 22, Township 114 North, Range 41 West

The DNR Bureau of Engineering contacted the following offices for corner information:

Secretary of State Yellow Medicine County Recorder Yellow Medicine County Highway Engineer

- 1867 U.S. General Land Office notes in the Secretary of State's Office describes this corner as a set post with charred stake, mound and pits.
- Surveyor's Record Book, on page 104, from the County Recorder's Office, contains a survey by Jonah Peterman, County Surveyor. Survey states the word "Bogus" at this corner.
- Surveyor's Record Book B, on page 163, from the County Recorder's Office, contains a collection of what was found at government section corners by John Norgaard, County Surveyor, in a township re-monumentation survey. Norgaard states this corner was "located at equal proportional distances from the northeast corner Section 10, the meander corner on the north side of lake between Sections 22 and 23 and 5300 feet west of the northeast corner Section 23". A 6" by 6" by 24" jasper granite stone was set at this location, top of monument level with ground. Page 33 of Surveyor's Record Book B is a township plat showing distances between government corners obtained from Norgaard's re-monumentation survey. This corner is also shown:
  - 1712 ft. from meander corner between Sections 22 and 23

5306 ft. from the northeast corner Section 15

1987 April, the DNR Bureau of Engineering conducted a search for this corner and found it to be in a cultivated field. No metal attraction was obtained, no occupation lines. Computed a lost position for this corner using the following corners resulting in the corresponding distances:

5296.83 ft. from the northeast corner Section 21

5343.14 ft. from the northeast corner Section 23

5320.83 ft. from the northeast corner Section 27

5320.17 ft. from the northeast corner Section 15

This lost position was then checked against GLO distances to feature calls with the following results:

1725.01 ft. to the water's edge of a lake

to the south, GLO to MC south 1702.8 ft.

135.81 ft. to the top of lake bank to the west

GLO to MC west 135.30 ft.

Analysis of the available information led the DNR Bureau of Engineering to conclude that the lost position should be used for the location of the corner, based on procedure and its position relative to GLO feature calls. Norgaard's method of establishing this corner is somewhat questionable. No evidence of his stone was found.