CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTHEAST Corner of Section 10 , Township 114 N , Range 38 W , 5th P.M.	
STATE OF MINNESOTA, County of YELLOW MEDICINE	
At the corner location shown on the sketch:	
\boxtimes On $8-2-93$ found a 6" x 6" GRANITE STONE, DOWN 2.0"	
DATE	
□ left monument as found, □ lowered monument, □ removed monument (explain) □ On 1-27-94 Placed o 3/4" x 24" REBAR WITH ALUMINUM CAP STAMPED □ DATE DATE	
DATE "DNR SURVEY MARKER", DOW	N 0.4, OVER STONE
SKETCH OF RE	FERENCE TIES
	NOTE:
+	MONUMENT IS ON E-W FENCE LINE EAST
	ON EXTENSION EAST OF A TREE LINE 22' NORTH OF SOUTH EDGE
\	OF GRANITE BED ROCK
	^F
DNR NAIL & DISC NE SIDE WOOD CORNER	
FENCE POST, UP 3.0° \(\sqrt{1}\) N 50° W	
68.28	
TWP RD	5 50° E
	SET PK NAIL TOP CENTER
5 46° W	NE END 12" CMP
52.52' 5 38° W 37.19'	
SET PK NAIL TOP CENTER 5W END 12" CMP	
1983 YELLOW MEDICINE CO.	
COORDINATE SYSTEM DNR NAIL & DISC NW SIDE POWER POLE	1 1
E = 629030.054 UP 1.0'	BEARINGS OBSERVED WITH COMPASS SNA01027.00.00.01
Statement of evidence relative to this corner lo	cation is on back of page. J.B.M. FEB '94
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of <u>Yellow Medicine</u>
my direct supervision.	I hereby certify that this document was filed in
SIGNATURE DATE	the Co. recorders office at 9:35 A.M. on the 22 day of June A.D., 1994
Registration No. 17005	22 day of June A.D., 1994 County Recorder
■ Land Surveyor, □ Professional Engineer	By,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 206996

Northeast Corner Section 10, Township 114 North, Range 38 West

- The DNR Bureau of Engineering contacted the following offices for information on this corner:

 MN. Secretary of State
 Yellow Medicine County Recorder and Highway Engineer
- 1864 The U.S. General Land Office field notes in the Secretary of State's Office describe this corner as a set post.
- Surveyor's Record Book, on page 21, on file in the Yellow Medicine County Recorder's Office contains a survey by Jonah Peterman, County Surveyor. Survey describes this corner as being found, but does not indicate what was found or set. Corner is shown to measure:
 - 40.37 chains from the north quarter corner Section 11
 - 40.37 chains from the east quarter corner Section 3
- 1892 Surveyor's Record Book, on page 55, on file in the Yellow Medicine County Recorder's Office contains a survey by Jonah Peterman, County Surveyor. Survey describes this corner as being found, but does not indicate what was found or set. Corner is shown to measure:
 - 40.37 chains from the north quarter corner Section 11
 - 40.12 1/2 chains from the east quarter corner Section 10
- 1901 Surveyor's Record Book B, on page 138, on file in the Yellow Medicine County Recorder' Office, contains a collection of what was found at government section corners by John Norgaard, County Surveyor, in a re-monumentation survey. Norgaard states: "Found stake set by adjoining landowners in the government mound several years ago." Set a 6" by 6" by 24" jasper granite stone at this location, top level with ground.
- 1993 August 2, the DNR Bureau of Engineering conducted a search for this corner and dug a 4 ft north-south by 2 ft. east-west hole at the intersection of roads north-south and west. At a depth of two feet found a 6" by 6" granite stone. Stone is at the intersection of said roads. Placed a DNR Survey Marker directly over the stone.

Analysis of the available information led the DNR Bureau of Engineering to conclude that the found stone marks the location of the corner.