CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTHEAST Corner of Section	. Township <u>114 N</u> ,Range <u>38 W</u> , <u>5</u> †h P.M.
STATE OF MINNESOTA, County of YELLOW MEDICINE	
At the corner location shown on the sketch:	
\boxtimes On $\frac{7-21-93}{\text{DATE}}$ found a $\frac{6" \times 6"}{\text{CUT STONE}}$, DOWN 1.4'	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Ø on 7-21-93 Placed a 3/4" x 12" IRON ROD WITH ALUMINUM CAP STAMPED	
"DNR SURVEY MARKER", OVER STONE, DOWN 0.3"	
SKETCH OF REFERENCE TIES	
l B	1
	NOTE: MONUMENT IS
SET PK ON TOP CENTER NORTH END 15" CMP	1' WEST OF CL N-5 ROAD 0.5' NORTH OF CL E-W ROAD
N 60° W	
35.01	
	L
	TWP RD
FIELD APPROACH	GRAVEL RD
SET PK ON TOP CENTER	1
5 66° W	
34.43'	u ··· (· · · · · · · · · · · · · · ·
2	5 66° E
1983 YELLOW MEDICINE CO.	DNR NAIL & DISC
COORDINATE 5Y5TEM N = 142031.223	SW SIDE POWER POLE UP 3'
E = 635088.967	BEARINGS OBSERVED WITH COMPASS
Statement of evidence relative to this corner location is on back of page. J.B.M. FEB '94	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of <u>Yellow Medicine</u>
my direct supervision Xovell R. Pommereum & 4-22-94	I hereby certify that this document was filed in the Co. recorders office at 10:20 A .M. on the
Registration No. 17005 DATE	22 day of June A.D., 19 94
Land Surveyor, Professional Engineer	County Recorder
	By,Deputy

Northeast Corner Section 26, Township 114 North, Range 38 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN. Secretary of State
Yellow Medicine County Recorder and Highway Engineer

- 1864 The U.S. General Land Office field notes in the Secretary of State's Office describe this corner as a post in mound with pits.
- 1901 Surveyor's Record Book B, on page 141, on file in the Yellow Medicine County Recorder' Office, contains a collection of what was found at government section corners by John Norgaard, County Surveyor, in a re-monumentation survey. Norgaard states: "Found stone at the intersection of road as used by me 5 years ago in the subdivision of adjoining sections. Set top of monument level with ground." Set a 6" by 6" by 24" jasper granite stone at this location. A plat of this survey shows this corner measures:

5306 ft. from the northeast corner Section 25 5338 ft. from the northeast corner Section 23

July 21, the DNR Bureau of Engineering conducted a search for this corner at the intersection of roads north-south and east-west. Found a nail down 0.2 ft. over a 6" carriage bolt, down 0.8 ft. Both were over a 6" by 6" cut granite stone down 1.4 ft. Set a DNR Survey Marker over the stone which was found to measure:

5325.40 ft. from the northeast corner Section 25 5330.55 ft. from the northeast corner Section 23

Analysis of the available information led the DNR Bureau of Engineering to conclude that the found stone marks the location of the corner.