Statement of evidence relative to this corner location is on back of page.

WMA00267

I hereby certify that this document and the data contained herein was prepared by me or under

License Number

- Professional Engineer ■ Land Surveyor,
- □ County Engineer ☐ County Surveyor,

OFFICE OF THE COUNTY RECORDER County of Yellow Medicine

I hereby certify that this document was filed in the Co. Recorder's Office at 10:20 B.M. on the 5 day of July A.D., 20.00

County Recorder Kan

DOCUMENT NO.

,Deputy

Northeast Corner of Section 27, Township 115 North, Range 44 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office Yellow Medicine County Recorder's Office Yellow Medicine County Highway Engineer's Office

Montevideo City Engineer's Office

1871 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a raised mound as per instructions.

1901 Surveyor's Record Book B contains John Norgaard's, County Surveyor, remonumentation notes for section corners in Yellow Medicine County. The following information is stated about corner on page 117:

located at the intersection of roads running north, south, east and west set a 6 inch by 6 inch by 24 inch long jasper granite level with the ground to mark corner

October, page 251 of a Surveyor's Record Book, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Survey shows corner but does not indicate what kind of monument was found or set. The corner is shown:

2640 feet from the north quarter corner of Section 26

5280 feet from the northeast corner of Section 26

5292 feet from the northeast corner of Section 22

1940 Section Corner Tie Book, obtained from the County Highway Engineer's Office, shows that a regular monument was found at corner. The following ties are shown to corner:

telephone pole, northwest, 40.8 feet fence post, east-southeast, 93.4 feet brace pole, southwest, 48.9 feet 10" Ash, north-northeast, 53.8 feet third fence post, north-northwest, 64.8 feet telephone pole, north-northeast, 104.1 feet third fence post, south-southwest, 69.5 feet

2000 May 1, DNR Bureau of Engineering hired a backhoe to dig for evidence of the corner. A 6" by 6" cut granite stone was found down 2.0 feet with a 6" section of rotted wood post on top of it. Searched for but found no evidence of the record ties. Set a 3/4" by 12" rebar with plastic cap stamped "MN DNR LS 17003" over the cut granite stone and found it to be:

at the intersection of the centerline of roads north, south, east, and west 5286.32 feet from the northeast corner of Section 26

5292.71 feet from the northeast corner of Section 22

Analysis of the above information led the DNR Bureau of Engineering to conclude that the 6" by 6" cut granite stone marks the location of the corner.