CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 19 Township 115 N. Range 46 W. 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 5/15/2000 found a 6" x 6" CUT GRANITE STONE, DOWN 2.5"	
☑ left monument as found, ☐ lowere	ed monument,
© 0n 5/15/2000 Placed a 3/4" x 24" REBAR	WITH ALUMINUM CAP STAMPED
"DNR SURVEY MARKER", DOWN 0.3', OVER STONE	
SKETCH OF RE	MONU IS 4' WEST OF & OF ROAD SOUTH AND 3' SOUTH OF & OF EAST-WEST ROAD
PUNCH HOLE TOP CENTER NORTH END 15" CMP ×	TOP CENTER
TWP. RD	
PUNCH HOLE TOP CENTER SOUTH END 15" CMP S60'W X37.54" BEARINGS ORSER	PUNCH HOLE TOP CENTER SOUTH END 18" CMP S70'E × 45.41' X VED WITH COMPASS PUNCH HOLE 1983 YELLOW MEDICINE COUNTY COORDINATES (1996 ADJUSTMENT) N= 180721.813 E= 359614.900
	6/12/2000
Statement of evidence relative to this corner loc	SNA02026
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of
my direct supervision 10/30/00 SIGNATURE 17003 License Number	the Co. Recorders Office at 8:45 A .M. on the day of NOV. 2 - 2000 A.D., 20 County Recorder
■ Land Surveyor, □ Professional Engineer	D.

By _______DOCUMENT NO.

☐ County Surveyor,

☐ County Engineer

Northeast Corner of Section 19, Township 115 North, Range 46 West

The Minnesota DNR Bureau of Engineering contacted the following for survey information:
Minnesota Secretary of State's Office
Yellow Medicine County Recorder's Office
Yellow Medicine County Highway Engineer's Office

- 1871 U. S. General Land Office notes, obtained from the Secretary of State's Office, show the corner marked with a wood post in a raised mound as per instructions.
- 1901 Surveyor's Record Book B, obtained from the County Recorder's Office, contains John Norgaard's, County Surveyor, remonumentation notes for section corners in Yellow Medicine County. The following information is stated about corner on page 131:

 found stake in the government mound set a 6 inch by 6 inch by 24 inch long jasper granite level with the ground to mark corner
- 1943 Section Corner Tie Book, obtained from the County Highway Engineer's Office, does not indicate what kind of monument was found or set at corner but the following ties are shown to it: third fence post, southeast, 72.3 feet corner fence post, northeast, 49.5 feet second fence post, southeast, 80.4 feet third fence post, southwest, 85.3 feet
- 2000 May 15, DNR Bureau of Engineering hired a backhoe to dig for evidence of the corner. A 6 inch by 6 inch cut granite stone was found down 2.5 feet. Searched for but found no evidence of the record ties. Set a 3/4 inch by 24 inch rebar with aluminum cap stamped "DNR SURVEY MAKER" over the cut granite stone and found it to be:
 - 3 feet south of the center line of an east-west Township Road
 - 4 feet west of the center line of a Township Road south

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found 6 inch by 6 inch cut granite stone marks the original location of the corner.