CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of Section 33 Township 114 N., Range 46 W., 5th P.M.	
STATE OF MINNESOTA, County ofYELLOW MEDICINE	
At the corner location shown on the sketch:	
On 10/10/2000 found a 9" TRIANGULAR FIELD STONE, DOWN 1.4"	
DATE	
■ left monument as found, □ lowered monument, □ removed monument (explain)  ■ On 10/10/2000 Placed a 3/4" X 12" REBAR WITH ALUMINUM CAP STAMPED	
DATE "DNR SURVEY MARKER", DOWN 0.4', OVER FIELD STONE.	
SKETCH OF REFERENCE TIES	
Ţ	
NAIL & DNR DISK	
IN TOP CENTER OF WOOD CORNER FENCE POST ×	NAIL & DNR DISK IN S SIDE OF POWER POLE, UP 3'
x x x	x x x
NORTH 38.11'	
	N 70° E 90.20°
	TWP RD
·	
YELLOW MEDICINE COUNTY COORDINATES, NAD 83	
1986 ADJ. N = 138298.308	
E = 367455.669	BEARINGS OBSERVED WITH COMPASS
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of Yellow Medicine
my diject superfision.	I hereby certify that this document was filed in the Co. Recorder's Office at 9:55 A.M. on the
SIGNATURE DATE	the Co. Recorder's Office at 3.33 A.M. on the 13 day of June A.D., 2001
License Number17003 ■ Land Surveyor, □ Professional Engineer	County Recorder Kay Nerdahl
☐ County Surveyor, ☐ County Engineer	By

## North Quarter Corner of Section 33, Township 114 North, Range 46 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office Yellow Medicine County Recorder's Office Yellow Medicine County Highway Engineer's Office

- 1871 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a raised mound as per instructions.
- 1913 A page in a Surveyor's Record Book, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Survey shows corner but does not indicate what kind of monument was found or set. The corner is shown:

2644 feet from the northeast corner of Section 33 2644 feet from the northwest corner of Section 33

2000 October 10, DNR Bureau of Engineering hired a backhoe to dig for evidence of the corner. A 9 inch triangular shaped stone was found down 1.4 feet. Set a 3/4" by 12" rebar with an aluminum cap stamped "DNR SURVEY MARKER" over the stone and found it to be:

on the center line of an east-west Township Road in line with a fence north 2651.66 feet from the northeast corner of Section 33 2648.94 feet from the northwest corner of Section 33

5.11 feet south and 1.41 feet west of the lost position

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found 9 inch triangular shaped stone marks the location of the corner.