	OF GOVERNMENT CORNER
NORTHEAST Corner of Section 33 , Township 114 N. , Range 46 W. , 5th P.M.	
STATE OF MINNESOTA, County of YELLOW MEDICINE	
At the corner location shown on the sketch:	
■ On 10/10/2000 found a 6" X 6" X 24" CUT GRANITE STONE, DOWN 1.5'.	
DATE	
■ left monument as found, □ lowered monument, □ removed monument (explain)	
On 10/10/2000 Placed a 3/4" X 12" REBAR WITH ALUMINUM CAP STAMPED	
"DNR SURVEY MARKER", DOWN 0.4', OVER STONE.	
SKETCH OF REFERENCE TIES	
<u> </u>	
NAL & DNR DISK IN	
SW SIDE OF POWER POLE,	
UP 3.5' \$ "	· -
N 40° W	·
44.40	
] TWP RD
S 40° W	S 40° E 45.86′
	NAIL & DNR DISK IN SW SIDE
NAIL & DNR DISK IN SE SIDE GOF POWER POLE, UP 4.0'	OF 5' HIGH WOODEN TELEPHONE JUNCTION BOX POST, UP 3.5'
YELLOW MEDICINE COUNTY COORDINATES, NAD 83 1986 ADJ. N = 138280.503	
E = 370107.274	BEARINGS OBSERVED WITH COMPASS
Statement of evidence relative to this corner lo	cation is on back of page. 2/21/01 WMA00190.00.00.01
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of Yellow Medicine
my direct supervision. SIGNATURE MATE	I hereby certify that this document was filed in the Co. Recorder's Office at 10:00 A.M. on the
License Number17003	13 day of <u>June</u> A.D., 2001 County Recorder <u>Kay Nerdahl</u>
■ Land Surveyor, □ Professional Engineer	By Sair Roblik Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 226148

Northeast Corner of Section 33, Township 114 North, Range 46 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office

Yellow Medicine County Recorder's Office

Yellow Medicine County Highway Engineer's Office

- 1871 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a raised mound as per instructions.
- 1901 Surveyor's Record Book B contains John Norgaard's, County Surveyor, remonumentation notes for section corners in Yellow Medicine County. The following information is stated about corner on page 203:

found the government mound and pits

set a 6 inch by 6 inch by 24 inch long jasper granite level with the ground to mark corner

1909 May, Surveyor's Record Book, page 198, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Survey shows that a stone monument was found at corner. The corner is shown:

2636 feet from the north quarter corner of Section 34

5272 feet from the northeast corner of Section 34

1913 A page in a Surveyor's Record Book, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Norgaard states:

"I could not find the jasper stone monument, after I got home and looking up the notes of a survey as I made in Section 34 I see the corner should probably be 10 or 12 feet farther east - but as my survey of these sections are in the southwest quarter it would not be but a little different at the center of the section"

The corner is shown:

2644 feet from the north quarter corner of Section 33

5288 feet from the northwest corner of Section 33

2643 feet from the east quarter corner of Section 33

Survey does not specify if the above distances are from the jasper stone monument or a point 10 or 12 feet west of it.

No A page in a Surveyor's Record Book, obtained from the County Recorder's Office, contains ties

Date to section corners. A description of what kind of monument was found or set at corner is not given but the following ties at shown to it:

corner fence post, northeast, 43.0 feet corner fence post, southeast, 43.9 feet

2000 October 10, DNR Bureau of Engineering hired a backhoe to dig for evidence of the corner. A 6 inch by 6 inch cut granite stone was found down 1.5 feet. Searched for but found no evidence of the record ties. Set a 3/4 inch by 12 inch rebar with aluminum cap stamped "DNR SURVEY MAKER" over the cut granite stone and found it to be:

at the intersection of the center lines of roads north, south, east and west

2651.66 feet from the north quarter corner of Section 33

5300.60 feet from the northwest corner of Section 33

2643.04 feet from the east quarter corner of Section 33

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found 6 inch by 6 inch cut granite stone marks the original location of the corner.