CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTHEAST Corner of Section 34 , Township 114 N. , Range 46 W. , 5th P.M.	
STATE OF MINNESOTA, County ofYELLOW_MEDICINE	
At the corner location shown on the sketch:	
■ On 10/10/2000 found a 6" X 6" X 24" CUT GRANITE STONE, DOWN 1.3'.	
DATE	
■ left monument as found, □ lowered monument, □ removed monument (explain)	
On 10/10/2000 Placed a 3/4" X 12" REBAR WITH ALUMINUM CAP STAMPED	
"DNR SURVEY MARKER", DOWN 0.2', OVER STONE.	
NAIL & DNR SKETCH OF REFERENCE TIES DISK IN S SIDE OF OPPOWER POLE, UP 4.5' II	
N 30. M €	
135.20'	
	TWP RD
<u> </u>	
NAIL & DNR DISK ON SE SIDE OF POWER POLE, UP 2.5'	
YELLOW MEDICINE COUNTY 61.57'	
E = 375386.325	BEARINGS OBSERVED WITH COMPASS
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of Yellow Medicine
my direct supervision SIGNATURE 17003	I hereby certify that this document was filed in the Co. Recorder's Office at 10:10 A.M. on the 13 day of June A.D., 2001
License Number17003 Land Surveyor,	County Recorder Kay Nerdahl
☐ County Surveyor, ☐ County Engineer	By <u>Jan Rohlir</u> Deputy

Northeast Corner of Section 34, Township 114 North, Range 46 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office

Yellow Medicine County Recorder's Office

Yellow Medicine County Highway Engineer's Office

- 1871 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a raised mound as per instructions.
- 1901 Surveyor's Record Book B contains John Norgaard's, County Surveyor, remonumentation notes for section corners in Yellow Medicine County. The following information is stated about corner on page 203:

found stone in the government mound

set a 6 inch by 6 inch by 24 inch long jasper granite level with the ground to mark corner

1909 May, Surveyor's Record Book, page 198, obtained from the County Recorder's Office, contains a survey by John Norgaard, County Surveyor. Survey shows that a stone monument was found at corner. The corner is shown:

2636 feet from the north quarter corner of Section 34

2638 feet from the east quarter corner of Section 34

5276 feet from the southeast corner of Section 34

No Section Corner Tie Book, page 4, obtained from the County Highway Engineer's Office, does not indicate what kind of monument was found or set at corner but the following ties are shown to it:

third fence post, southeast, 76.5 feet

first fence post, northeast, 80.5 feet

hub, northwest, 84.4 feet

2000 October 10, DNR Bureau of Engineering hired a backhoe to dig for evidence of the corner. A 6 inch by 6 inch cut granite stone was found down 1.3 feet. Searched for but found no evidence of the record ties. Set a 3/4 inch by 12 inch rebar with aluminum cap stamped "DNR SURVEY MAKER" over the cut granite stone and found it to be:

at the intersection of the center lines of roads north, south, east and west

2635.81 feet from the north quarter corner of Section 34

2640.90 feet from the east quarter corner of Section 34

5281.80 feet from the southeast corner of Section 34

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found 6 inch by 6 inch cut granite stone marks the original location of the corner.