CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
E 1/4 Corner of Section 30 , Township 116 , Range 39 , 5TH P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
☑ On 1-4-2012 found a REBAR W/CAP #19092 AT GROUND SURFACE	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
☐ On placed a	
SKETCH OF REFERENCE TIES	
NE COR TALL POST W/SCATTERED STONES	
	SET #48998 CAP ON TOP OF POST
	52"E 2645.7
	ର୍ଷ ଆ ଅ
xx	<u> </u>
مار المار	
SECTION 30	
T116N - R39W	FD REBAR SECTION 29
TITON - R39VV	/ W/CAP #19092 \ T116N - R39W
/ -1-45 /	
TOP OF HILL	
PASTURE	PASTURE
PAGIGIE	
ig	
OHP	OHP OHP
MN STATE PLANE SOUTH COORDINATES NAD83(96):	
143	
MN STATE PLANE SOUTH COORDINATES NAD83(96): SE COR	
N:997809.40 E:2213425.85	FD. § REBAR
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under my direct supervision.	County of I hereby certify that this document was filed in
	the Co. Recorders office atM. on the
6 Myn 1/4/2012	doy of A.D., 20
Registration No. 48998	County Recorder
□ Land Surveyor, □ Professional Engineer	By, Deputy
	DOCUMENT NO.
☐ County Surveyor, ☐ County Engineer	

STATEMENT OF EVIDENCE

The East Quarter Corner of Section 30, Township 116 North, Range 39 West of the 5th Principal Meridian.

U.S. General Land Office notes show corner marked a wood post in a mound with pits as per instructions. (1865)

In 1865, W.J. Neely established the lines of this township, as per the information on the copy of the original Township Plat as provided by the Register of Deeds. No other information exists was able to be found. Original notes were unable to be found.

On 1-4-12, a survey crew from Ulteig Engineers found and accepted a Rebar with cap #19092, and set new ties as shown. Monument was accepted in a non-filed survey by Roy Marihart. Since no public record is available for this monument, it is the opinion of Ulteig Engineers that the location of this monument correctly perpetuates the position of the original corner based upon local use and occupation, as well as corroborative evidence in the form of distances to adjacent corners.

Uteig Engineers contacted the following for survey information:
Yellow Medicine County Recorder's Office
Yellow Medicine County Highway Engineer's Office
Chippewa County Recorder's Office
Chippewa County Highway Engineer's Office
Marihart Land Surveying
K.B. MacKichan and Associates, Inc.
Bonnema Surveys of Willmar
West Central Land Services, Inc. of Willmar

N/C UIteig 5701 S. Corporate Place Siwx Falls, SD 57108

Doc# 254405 Fee: \$0.00 2 Pages Property & Public Services

Property & Public Services
Property Records Division
Yellow Medicine County, Minnesota
I hereby certify that the within instrument
was filed on January 13, 2012 at 10:00 AM

Janel Timm, Yellow Medicine County Recorder

Deputy Deputy