Doc# 257664 Fee: \$0.00 2 Pages

Property & Public Services
Property Records Division
Yellow Medicine County, Minnesota
I hereby certify that the within instrument
was filed on May 7, 2013 at 11:05 AM

Janel Timm, Yellow Medicine County Recorder

Nelvico Blood Deputy

N/C BONNEMA SURVEYS INC PROFESSIONAL LAND SURVEYING 1809 22ND STREET SW SUITE 104 WILLMAR MN 56201

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
East Quarter Corner of Section 3 , Township 114 , Range 45
Fifth Principal Meridian, State of Minnesota, County of Yellow Medicine
At the corner location shown on the sketch:
On July 19, 2012 found a 3/4" x 14" iron pipe 1.0' below the road surface, and also 3/4"x16" iron bolt
and a %" square x 10" iron bolt, along side each other 2.5' below surface, and an old wood stake 3.7' below the surface [left monument as found
☐ left monument as found ☐ lowered monument ☐ removed monument (explain) X On March 1, 2013 placed a Cast iron capped 2" x 30" telspar monument at the location of the found
DATE 3/4" x 16" bolt and the ½" square x 10" iron bolt along side each other
Peo
X on top RCP Culvert
RCP Culvert
Driveway
Field Approach
77.20.
— Section 3— — — — — — — — — — — — Section 2—
—Section 3— — — — — — — — — — — — — — Section 2—
Section 3————————————————————————————————————
Section 3 The Telspar monument is 0.25' North and 1.65' West of the location of the 34" Iron Pipe (now removed)
Section 3 The Telspar monument is 0.25' North and 1.65' West of the location of the 34" Iron Pipe (now removed)
Section 3 The Telspar monument is 0.25' North and 1.65' West of the location of the 34" Iron Pipe (now removed)
Section 3 The Telspar monument is 0.25' North and 1.65' West of the location of the 34" Iron Pipe (now removed)
Section 3 The Telspar monument is 0.25' North and 1.65' West of the location of the 34" Iron Pipe (now removed) Rail Road Spike Yellow Medicine County Coordinates (1996 Adjustment) MnDot Project Coordinates (Lyon County Coordinates 1996 Adjustment)
The Telspar monument is 0.25' North and 1.65' West of the location of the \(^3\)4" Iron Pipe (now removed) Yellow Medicine County Coordinates (1996 Adjustment) N= 161881.89 E= 407288.41 Statement of evidence for this corner location is on back of this page.
Yellow Medicine County Coordinates (1996 Adjustment) N= 161881.89 E= 407288.41 Statement of evidence for this corner location is on back of this page. The Telspar monument is 0.25' North and 1.65' West of the location of the ³ 4" Iron Pipe (now removed) MnDot Project Coordinates (Lyon County Coordinates 1996 Adjustment) N= 288129.24 E= 394287.10 Statement of evidence for this corner location is on back of this page. I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision
Yellow Medicine County Coordinates (1996 Adjustment) N= 161881.89 E= 407288.41 In The Telspar monument is 0.25' North and 1.65' West of the location of the ½" Iron Pipe (now removed) MnDot Project Coordinates (Lyon County Coordinates 1996 Adjustment) N= 288129.24 E= 394287.10 Statement of evidence for this corner location is on back of this page. I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota.
Yellow Medicine County Coordinates (1996 Adjustment) N= 161881.89 E= 407288.41 Statement of evidence for this corner location is on back of this page. The Telspar monument is 0.25' North and 1.65' West of the location of the ³ 4" Iron Pipe (now removed) MnDot Project Coordinates (Lyon County Coordinates 1996 Adjustment) N= 288129.24 E= 394287.10 Statement of evidence for this corner location is on back of this page. I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision

STATEMENT OF EVIDENCE

East Quarter Corner Section 3, T114N-R45W

1871

L. Harrington was contracted by the United States Government Land Office to perform the Original Public Land Survey in this township. He records in his field notes, "Set a post for 1/4 sec. cor, raised mound as per instructions."

Dec 16, 1920

F.R. Kline, Land Surveyor, prepared the record plat entitled, "OUTLOTS H TO V INCLUSIVE TO THE TOWN OF CANBY" on file in the office of the Yellow Medicine County Recorder. Kline shows an "Iron bolt" at the corner position and dimensions to the center of section.

August 1926

John Norgaard, County Surveyor, records in Yellow Medicine County Survey Record Book, page 505, "I.B." at the corner position.

Nov 18, 2010

Daniel L Bueltel, RLS 43844, (Bueltel project No. 10-4071), records that he found a "3/4" pipe," while doing a survey in Section 3.

July 19, 2012

Duane A. Bonnema, Land Surveyor #14895, while doing a remonumentation survey for the Minnesota Department of Transportation, found a 3/4" x 14" Iron Pipe at the road surface. He dug a 4.1' deep hole that covered an area extending 4.0' north, 8.0' south, 5.0' east, and 3.0' west of the found 3/4" x 14" iron pipe. The original top soil was observed to be at a depth of 2.2' below the surface. At a depth of 2.5' he found a 3/4" x 16" bolt with another 1/2" x 1/2" x 10" square bolt alongside. I.5' west of the bolts the remnants of the wooden stake were found. This wood stake may have been used as a flag pole to run the eastwest quarter line. Either the bolt or the square bolt are evidently the "iron bolt", noted by F.R. Kline in his 1920 survey work, and John Norgaards note "IB" in 1926. A 2" square by 30" long iron telspar monument was placed at the location of the 3/4" x 16" bolt and 1/2" square 10" bolt. This Telspar monument is 0.25' north and 1.65' west of the location of the 3/4" Iron Pipe found at the road surface.