CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  North Quarter Corner of Section 23 Township 114N, Range 40W, 5th P.M.	
STATE OF MINNESOTA, County ofYellow Me	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
A 0.1070	
On Aug. 9,19/2 placed a Minnesota Hi  Onte  (flush), guarded by a mound of stone	
SKETCH OF REFERENCE TIES	
-N-	
S E C.	14 
BRANCH 2 OF JUD. DT. 24	
61.34	BOTTOM OF STEEL FENCE
YELLOW STEEL Fence Post . W.S.W.	POST E.
SEC.	23
-	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS  County of Yellow Medicine
my direct supervision.	I hereby certify that this document was filed in the Reg. of Deeds office at/!:40 A.M. on the
SIGNATURE 12/4/76 DATE	Register of Deeds Fisiman & Opdahl
Registration No. <u>3236</u> Land Surveyor, Professional Engineer	By Kay Nerdall ,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 162745

## Statement of Evidence: NORTH QUARTER CORNER SECTION 23, T114N, R40W

The original Public Land Survey was run in 1864 and a wood post was set in a mound with pits to mark the corner.

In 1940 a telephone pole was found at the location of the corner. The origin of the pole could not be determined. It has since been removed during the construction of a drainage ditch.

This corner was set at the lost location. It is in agreement with the centerline of the drainage ditch to the north and west and a fence line to the east.

For details of survey analysis and 1972 electronic survey measurements, see Survey Report for S.P. 4203 and 8701 on file in the Surveys Section, Minnesota Highway Department, Willmar, Minnesota.