Index	No	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Northeast Corner of Section 6 , Township 115N , Runge 39W , 5th P.M.			
STATE OF MINNESOTA, County of Yellow Medicine			
At the corner location shown on the sketch:			
On found a			
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)			
On Dec. 22, 1976placed a Minnesota Highway Department cast iron monument at road surface.			
SKETCH OF REFERENCE TIES			
SECTION 31	SECTION 32		
-N-	COPPER NAIL & DISC IN TELEPHONE CABLE PED. MARKER POST 61.75 N.E. (UP 2.0')		
	€ T.H. 23		
COPPER NAIL & DISC IN SOUTHEAST SIDE OF POWER POLE 59.33 S.W. UP 4.0' SECTION 6	SECTION 5		
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.    About Montagesh	OFFICE OF THE VELLOW MEDICINE COUNTY County of Yellow Medicine  I hereby certify that this document was filed in the Reg. of Deeds office at 12:05 P. M. on the 42 day of October A.D., 19 27 COUNTY RECORDER Mannant Operation  By Kay Nordall Deputy DOCUMENT NO. 170322		
M.H.D. FORM NO. 2105			

## Statement of Evidence: N.E. Cor. Sec. 6, T115N, R39W.

The original Public Land Survey of the township line was completed in 1858 by W. J. Neely. A wood post was set and coal was deposited in a mound of dirt with trenches and pits to mark the corner.

In 1901, John Norgaard, County Surveyor, found a stone set in the government mound by adjoining land owners when the mound could still be seen. He set a 6"x6"x24" granite monument level with the ground at this location.

1931 Minnesota Highway Department notes show that a granite monument was found marking the corner. The notes show the corner to be on the centerline of T.H. 23 at engineer's station 130+63.0.

In 1976 a Mn/DOT survey crew set a cast iron monument at said engineer's station 130+63 to mark the corner. Being the corner is in a concrete pavement, no excavation was made for the corner.

This is accepted as the position for the government corner because it nearly fits occupation lines, that is, it is on the centerline of T.H. 23 and 5 feet east of the centerline of a north/south township road. Also, the 1931 notes were very definite in showing the location of the corner.

For details of survey analysis and 1976 electronic measurements, see the Survey Report for S.P. 8702 and S.P. 8706, Jct. T.H. 23 and T.H. 67 - 3 miles S.W. of Granite Falls, on file with the Surveys Section, Mn/DOT, Willmar, MN, 56201.

