☐County Engineer

☐ County Surveyor

## STATEMENT OF EVIDENCE:

NORTHEAST OF SECTION 30, T115N, R46W, 5TH PM

1871 Corner was originally established by the U.S. General Land Office as a post set in raised mound.

1901 Surveyors Record Book B contains a survey by John Norgaard, County Surveyor, in which shows a found stake in government mound and set a 6"x6" jasper granite monument.

1903 Surveyors Record Book contains a survey by John Norgaard, County Surveyor, in which shows a jasper granite monument in place at the corner location.

Undated Resurvey completed in which a stake and government mound were found and set top of monument level with ground.

1997 County Engineers field book for County Rd E-3 shows a field stone in place over a found stone with the following ties: power pole SE 60.5'

power pole NE 60.6' Station 39+37.09

2000 DNR excavated for the corner and found a bridge spike over a 12'x6"x6" field stone which was over a 6"x6" cut granite stone. A 3/4" rebar with DNR SURVEY MARKER aluminum cap was set over found monuments and a corner record was filed dated 10/30/00.

2014 Bueltel-Moseng Land Surveying completed a survey in Section 29 in which they found a DNR monument in place at the corner location.

2017-10-27 Westwood PS searched the area and found a 3/4" rebar with aluminum cap DNR SURVEY MARKER per 2000 corner record. Accepting as corner location and set 3 reference ties.