CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTH QUARTER Corner of Section 27, Township 115 N., Range 44 W., 5th P.M.	
STATE OF MINNESOTA, County of <u>YELLOW MEDICINE</u> .	
At the corner location shown on the sketch:	
☑ On <u>6-7-2023</u> found a <u>2"X3" AXLE SHAFT DOWN 2.0' ON CL EW</u>	
date AND FENCE EXTENSION SOUTH	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
☑ On7-19-2023 placed a 5/8 INCH BY 18" LONG REBAR WITH CAP MARKED	
date	
MN LS 48258 AT THE LOCATION SHOWN BELOW.	
SKETCH OF REFERENCE TIES	
SKETOH OF KEI EKENGE HES	
	4
N ¹ CORNER	<i>N</i>
SEC.27, T.115, R.44	NE CORNER SEC. 27, T.115, R. 44
SET § INCH CAPPED REBAR	3/4" REBAR MN DNR LS 17003 PER DOC. NO. 223190
OVER DEEP SET AXLE SHAFT	
SET 60D SPIKE W.	SET 60D SPIKE W.
NAIL & DISK 3>.97 \ 74.59	NAIL & DISK
S88°01'31"E 2649.89	S88°02'54"E
730.1983	2649.15
SET 60D SPIKE W. 5 1 / 6	SET 60D SPIKE W.
NW CORNER	NAIL & DISK
SEC. 27, T.115, R. 44	
ਵਾ IRON WITH SEAL # 43844 PER DOC. NO. 245322	
5297.75	
- 5297.78 S01°55'17	S¼ CORNER
Minnesota State Plane Coordinate System	SEC. 27, T.115, R. 44
South Zone, US Feet, Grid Scale 1.0	SET § "IRON WITH SEAL # 48258
NAD83 (2011) N = 972170.75	
E = 2067581.28	NOT TO SCALE
Statement of evidence relative to this corner location is on back of this page.	
I hereby certify that this document and the data	
contained herein was prepared by me or under my	Doc# 280860 Fee: \$0.00 2 Pages
direct supervision.	Property & Public Services Property Records Division
In M. Jan 9-5-2002	Yellow Medicine County, Minnesota I hereby certify that the within instrument
SIGNATURE DATE	was filed on September 11, 2023 at 11:10 AM
Registration No. <u>48258</u>	Janel Timm, Yellow Medicine County Recorder
☑ Land Surveyor ☐ Professional Engineer	By Marit Nordang Deputy
□ County Surveyor □ County Engineer	Deputy

STATEMENT OF EVIDENCE

KLJ contacted the following for survey information

MN GLO/BLM original survey records
Yellow Medicine County Recorder's Office
MNDOT office in Willmar
Yellow Medicine County Highway Engineer's Office
Bonnema Surveys, Inc. of Willmar
O'Malley & Kron Land Surveyors, Inc. of Willmar
Bueltel—Moseng Land Surveying of Marshall
Marihart Surveying, P.A. of Dawson
Egan Field & Nowak, Inc of New Brighton
E.G. Rud & Sons, Inc. of Hutchinson

In September, 1871, Lewis Harrington, General Land Office Deputy Surveyor performing the original survey of the subdivision lines set a wood post in a raised mound.

On June 7, 2023, KLJ dug and found an axle shaft down 2.0' on centerline East West and fence line extension South. KLJ found no evidence of the original corner or other corner monuments and accepted the monument as the North $\frac{1}{4}$ corner.

On July, 19, 2023, KLJ set a \S " rebar with MN LS 48258 down 0.50' below grade. Set monument in same location as found axle shaft due to excessive depth.