CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
NORTH QUARTER Corner of Section 26, Township 115 N., Range 40 W., 5th P.M.
STATE OF MINNESOTA, County of <u>YELLOW MEDICINE</u> .
At the corner location shown on the sketch:
On found a
☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)
☐ On
date MN LS 48258 AT THE LOCATION SHOWN BELOW.
CVETCH OF DECEDENCE TIES
SKETCH OF REFERENCE TIES
N $\frac{1}{4}$ CORNER \mathcal{N}
SEC. 26, T.115, R. 40 SET MN LS 48258
SET 60D SPIKE W.
NAIL & DISK SET 60D SPIKES W. NE CORNER NAIL & DISK SEC. 26, T.115, R. 40
5/8" REBAR LS 23021 PER DOC. NO. 246201
2655.09 S88°36'30"E
N88°36'30"W 2655.09
NW CORNER SEC. 26, T.115, R. 40 SET NAIL & DISK
1 ¼ " PIPE LS 11943 PER DOC. NO. 197342 SW FACE OF POWER POLE UP 3.0'
V1 -
\$300 \$\frac{530}{5}
Minnesota State Plane Coordinate System
SEC. 26, T.115, R. 40 South Zone, US Feet, Grid Scale 1.0 NAD83 (2011) SEC. 26, T.115, R. 40 3/4" PIPE LS 14895 PER DOC. NO. 183650
N = 968987.41 E = 2199917.31
Statement of evidence relative to this corner location is on back of this page.
I hereby certify that this document and the data
contained herein was prepared by me or under my direct supervision. Doc# 280885 Fee: \$0.00 2 Pages Property & Public Services
Property Records Division Yellow Medicine County, Minnesota I hereby certify that the within instrument
Yellow Medicine County, Minnesota I hereby certify that the within instrument was filed on September 11, 2023 at 1:15 PM
Yellow Medicine County, Minnesota I hereby certify that the within instrument Was filed on September 11, 2023 at 1:15 PM

STATEMENT OF EVIDENCE

KLJ contacted the following for survey information

MN GLO/BLM original survey records
Yellow Medicine County Recorder's Office
MNDOT office in Willmar
Yellow Medicine County Highway Engineer's Office
Bonnema Surveys, Inc. of Willmar
O'Malley & Kron Land Surveyors, Inc. of Willmar
Bueltel—Moseng Land Surveying of Marshall
Marihart Surveying, P.A. of Dawson
Egan Field & Nowak, Inc of New Brighton
E.G. Rud & Sons, Inc. of Hutchinson

In September, 1864, C.E. DAVIS & J.W. WEBB JR., General Land Office Deputy Surveyors performing the original survey of the subdivision lines set a wood post, in mound with pits.

On June 21, 2023, KLJ searched the straight line single proportion position and nothing was found. A search was made a chain each way and nothing was found. The monument was likely obliterated.

on July, 19, 2023, KLJ set a \S^n x 18" rebar with MN LS 48258 down 0.30' which falls at the straight line single proportion on the centerline of the bituminous highway. There is no occupation north or south as it's tillable land.